




P.O. Box 670 Hoschton GA 30548 USA
Tel: (706) 654-3232 Fax: (706) 654-3888
E-Mail: sales@ibis-usa.com <http://www.ibis-usa.com>

Technical Bulletin DSR-020311 page 1

NOTE: All energy... electrical, pneumatic, hydraulic, etc. must be disabled with lockouts in place !

D130 DOFFER SCREEN REPLACEMENT




REMOVE GUARDS ON BOTH SIDES TO GAIN ACCESS TO NYLOCK NUTS HOLDING SCREEN

REMOVE THESE TWO PANELS TO GAIN ACCESS TO THE DOFFER SCREEN



P.O. Box 670 Hoschton GA 30548 USA
Tel: (706) 654-3232 Fax: (706) 654-3888
E-Mail: sales@ibis-usa.com <http://www.ibis-usa.com>

Technical Bulletin DSR-020311 page 2



**REMOVE BOLTS FROM SCREEN MOUNTING
PLATE ON EACH SIDE OF SEPARATOR (16
TOTAL).**

**REMOVE SCREEN ASSEMBLY THRU
OPENING CREATED IN STEP ONE**

INSTALL NEW SCREEN ASSEMBLY

**REPLACE PANELS AND GUARDS REMOVED
IN STEP ONE**